FIELD INSPECTION REPORT

Date of Inspection: 10.12.2020		District: Samastipur		
Division: RWD Dalsinghsarai		Length(km): - &	Length(km): - 2.300 /au	
-	ne of Road: Gandhi chowle MH	103 to laishan	Pur	
-	eme / Programme: MAINTENANCE	NEW MR 20		
	rage No:	Road Id No:		
	us of the Project: Ongoing/Completed/Under	Maintenance - ang	einz.	
	k is a case of: New Connectivity/ Up g	radation/ Maintenance _	up gradation.	
SI. No	Parameters to be Checked		Remarks	
1	Pavement			
a)	Road Junction Condition		_	
b)	Condition of Surfacing		-	
c)	Riding Quality		_	
d)	Road Camber	-		
e)	Whether free from defects such as visible cra aggregates in case of CC Pavement	acks, exposed		
f)	Construction Joint provided or not(CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		_	
c)	Condition of railings/slab/approach for Bridge		_	
3	Road Furniture			
a)	Whether sign boards/information/cautionary stones/Pavement road markings are provided	Board/km & 200m I and maintained	main bend Ry	
4	Compliance History			
a)	Status of ATR's & any others		NO	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SH
Unsatisfactory(U)	

(Signature)

NAME: And prosect DESIGNATION: 15