

FIELD INSPECTION REPORT

Date of Inspection: 10/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.00 Km
Name of Road : गुनाई बसही चौक से लगनदेव सखी के चार तरफ		
Scheme / Programme: MAINTENANCE		
Package No:		Road Id No:
Status of the Project: <u>Ongoing</u> /Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	"
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	"
f)	Constraction Joint provided or not(CC Pavement)	"
g)	Compaction of flank/slope & raincuts if any	"
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	"
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	"
c)	Condition of railings/slab/approach for Bridge	"
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	"
4	Compliance History	
a)	Status of ATR's & any others	"

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

NAME:

DESIGNATION :

Hanaraj Prasad
J. E.

(Signature) 10/12/20