FIELD INSPECTION REPORT

,	rate of Inspection: 18 13		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km) La 3 (5 1285)		
N	ame of Road : - erect o	CONTRACTOR OF THE PARTY OF THE	मिर्जापर जाल हर	0 तहा वस्त
PATRICIA DE	AND DESCRIPTION OF THE PROPERTY OF THE PROPERT	INTENANCE		and the second s
NO COLUMN	ckage No:		Road Id No:	
Sta	itus of the Project: Ongoin			
NAME OF TAXABLE PARTY.	ork is a case of: Nev	v Connectivity/ Up	gradation/ Maintenance	
SI. No	Parameters to be Checked			Remarks
<u> </u>	Pavement			
a)	Road Junction Condition			NIA
b)	Condition of Surfacing			,,
e)	Riding Quality			11
d)	Road Camber			11
:)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			11
<u>/</u>)	Constraction Joint provided or not(CC Pavement)			17
()	Compaction of flank/slope & raincuts if any		у	//
	Cross Drainage			
)	Condition of head walls in Hume pipe culverts including its painting			")
)	Condition of Abutment & Wing walls , Slab in RCC culverts		b in RCC culverts	71
	Condition of railings/slab/approach for Bridge			/)
	Road Furniture			*
S	Whether sign boards/infortones/Pavement road mar	mation/cautionar kings are provide	y Board/km & 200m ed and maintained	"
C	ompliance History			
-	atus of ATR's & any other	ers		,,

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

(Signature)

Shanayay prosad

DESIGNATION:

T.E.