


FIELD INSPECTION REPORT

Date of Inspection: 10/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.00 km
Name of Road : PND 4th St/007 APHC 21/35 JB 1		
Scheme / Programme: MAINTENANCE		
Package No: PND 4th St/007		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	N/A
b)	Condition of Surfacing	11
c)	Riding Quality	11
d)	Road Camber	11
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	11
f)	Constraction Joint provided or not(CC Pavement)	11
g)	Compaction of flank/slope & raincuts if any	11
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	11
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	11
c)	Condition of railings/slab/approach for Bridge	11
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	11
4	Compliance History	
a)	Status of ATR's & any others	11

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	


 (Signature) 10/12/20

NAME: Manoj Prasad
 DESIGNATION: J.E.