

FIELD INSPECTION REPORT

Date of Inspection: 9.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 2.55	
Name of Road : PWD Road to Choudaule (Chapra Road)		
Scheme / Programme: MAINTENANCE	MR New	
Package No:	Road Id No:	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance		
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	—
b)	Condition of Surfacing	—
c)	Riding Quality	—
d)	Road Camber	—
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	—
f)	Constraction Joint provided or not(CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained <i>Not fixed</i>	U
4	Compliance History	
a)	Status of ATR's & any others	

Stipulated date of Comp is 19/11/20 but till now Bt work not started

Overall Rating :

Contractor debarred for delay in work.

Satisfactory(S)	—
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	U

M
09/12/20
(Signature)

NAME: Mananjan Kumar
DESIGNATION : AE