

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Patna
Division : Patna		Length (km): 2.30 km
Name of the Road: NH30A to Bankipur		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/2019-20/PATNA/04		Road Id No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance		
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☒ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒ Progress
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SSRII NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRII NA
c)	Condition of railings/slab/approach for Bridges	SSRII NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating ☒ In 400 m surface works are done along road in satisfactory manner.

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Himanshu Ray
(Signature)

NAME: Himanshu Ray
DESIGNATION: Assistant Engineer