

FIELD INSPECTION REPORT

Date of Inspection : 10.12.2020	District: East Champaran
Division : R.W.D(W) Dhaka	Length (km): 0.500
Name of the Road: Dhaka Phulwariya Road to Khairwa.	
Scheme/Programme: MAINTENANCE	New - 3054
Package No.: MR-N/19.20/Dhaka-15	Road Id No.: 31786103279
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NOTE:- Some Parts of Roads in 1st km & are damaged due to flood during Rain/Flood in year 2019-20 & 2020-21. Revised estimate submitted for sanctioned. But road is Mafarable. (Signature)

NAME: Shetchmural Hods.

DESIGNATION: A-E

Signature
10/12/2020
ER