

FIELD INSPECTION REPORT

Date of Inspection : 10.12.2020		District: East Champaran.
Division : R.W.D (W) Dhaka		Length (km): 2.00
Name of the Road: R.E.D Path Mathiya Mohan Patahi Road to choudhry Hanuman Mandir to Serha Tola.		
Scheme/Programme: MAINTENANCE New 30.54		
Package No.: MR.N/19.20/Dhaka-15	Road Id No.: 31708607038	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	N/A
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NOTE:- Some parts of Road in 1st KM & 2nd KM are damaged due to flood during Heavy Rain/Flood in year 2019-20 & 2020-21. But road is Motorable. & Revised estimated Submitted & Processed for sanctioned.

NAME: Shesh Nivul Hoda

10/12/2020

DESIGNATION: A.E

(Signature)