## FIELD INSPECTION REPORT

Date of Inspection: 09	112 2020	District: East Champa	ran
		Length (km): 2.0 Km	
Name of the Road:	Dah to I	Madhopur	
Scheme/Programme:	MAINTENANCE	(New Maintenance P Road Id No.: 217 DOGO	olicy)
Package No.:	Ongoing/Completed	/Under Maintenance	4132
Status of the Project:	New Connectivity/L	p gradation/ Maintenance	
Work is a case of:			
Sl. No. Parameters to be checked			Remarks
1. Pavement			-
a) Road Junction co	Road Junction condition		
b) Condition of Sur	Condition of Surfacing		
c) Riding Quality	Riding Quality		
d) Road Camber	Road Camber		
e) Whether free f aggregates in case	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f) Contraction Joint	Contraction Joints provided or not (CC Pavement)		
	Compaction of flank/slope & raincuts if any		
2. Cross Drainage			
	Condition of head walls in Hume pipe culverts including its painting		
b) Condition of Abu	Condition of Abutment & Wing walls, Slab in RCC culverts.		
	Condition of railings/slab/approach for Bridges		
Road Furniture			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
Compliance Histo	jry .		
Status of ATR's &	any others	^	
. NA-	Tende	er disposal Proce	35
rall Rating : S	atisfactory (S)		
		equires Improvement (SRI)	

NAME: Rounchandra laswass DESIGNATION: Executive Engineer

Unsatisfactory (U)

09112 2020 (Signature)

09/12/20