

FIELD INSPECTION REPORT

Date of Inspection :- 09.12.20		District :- Khagaria	
Division :- Khagaria		Length (Km) :-	
Name of Road :- Haripur Panchayat ke kista Mahaveer Asthane firanga Astham Hole Hue Baiowa Mushahari Doh Cachanikhera			
Scheme/Programme :- New M/R		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- In progress		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c)	Condition of railing /slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Plaque at road markings are provided and maintained	Yes/No
4.	Construction History	
a)	State of WATER's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 09.12.20
 J. G. Alauli