

# Inspection of Roads Under MR (3054) In Chauka Block

## FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Buxar	
Division : Buxar		Length (km): 1.592	
Name of the Road: Buxar - Sasaram Road to Sonba (Jatilpur) Under MR(3054) New Policy			
Scheme/Programme:		MAINTENANCE	
Package No.: MR-N/13-20 Buxar/19		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	<b>Pavement</b>		
a)	Road Junction condition		✓/U
b)	Condition of Surfacing		✓/U
c)	Riding Quality		✓/U
d)	Road Camber		✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		✓/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		<del>S/SRI/U</del> N.A.
c)	Condition of railings/slab/approach for Bridges		<del>S/SRI/U</del> N.A.
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓/Yes/No
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		No.

Overall Rating :

Satisfactory (S)	' S '
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/20  
AC  
M. Basad  
(Signature) 03.12.2020

NAME: Maya Nand Basad

DESIGNATION: J.E.