FIELD INSPECTION REPORT

112ta of	I	-	OHOR IGH ORT	1	
Division	Inspection: 6	4-12-2020	District: Munger	•	
Ning			1 1 1 2 2 8		
Name o	I the Road: NH	So Bilahari Arthur	Length (km): 0.628.		
Scheme	Programme:	MAINTENANCE	Length (km): 0.625:	otehua Kama	
гискав	c No.:	The state of the s	1-14-14000	i k	
Status of the Project:		Ongoing/Complete	Road Id No.: 1633.	: :	
Work is a case of:		Ongoing/Completed/Under Maintenance / 'n tender proces. New Connectivity/Up gradation/ Maintenance			
SI. No.	建四层层		P Bradation Maintenance		
1.	Payement	Parameters to	be checked	··· Remarks	
a)	Road Junction condition				
b)	Condition of Surfacing			S/U	
c) -	Riding Quality			s/fu	
(b)	Road Camber			\$I/U	
e)	Whether free from defects such as which			STAX	
	Yes/No				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	e			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRIAT	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SENTAX	
c)	Condition of railings/slab/approach for Bridges			6/SRI/U	
3.	Road Furniture				
a) -	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			YONNA	
4.	Compliance Ili				
a)	Status of ATK's	& any others = The	sovad is intender proc	2400	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ravi Shankor Mandal. J. E.

Monday 7000 04.12.7000 (Signature)

NAME: