## FIELD INSPECTION REPORT

	f Inspection :	NA District: Lakuisaroai	
Divisio		Seroal Length (km): 1.00 Km	
	of the Road:     	Murvalia to Pathua MA	
Package		MAINTENANCE   NA   Road Id No.:	
-	f the Project:	Ongoing/Completed/Under Maintenance	·
	a case of:	New Connectivity/Up gradation/ Maintenance	·
Sl. No.		Parameters to be checked	Remarks
<b>1.</b> 2011 - 20	Pavement		rya n
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Draina		(1)
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furnitu	re	
a) ~	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		
Overall	Rating :		, 4
		Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	

Road is Sanction under New Mains, foliay 2018. Road is under Technical Bid.

(Signature)

NAME:

ne