## **FIELD INSPECTION REPORT**

Date of Ir	nspection: The London	District: unarava	
Division:		Length (Km):- 24 4m	
Name of	Road: P.W.D. Rood Jalk	District: Majara  Length (Km): 2,40  auna to Gorgiya	
Scheme/Programme:- New-HR.		Maintenance	
Doolrogo No.		Road ID No.:-	
Status of Project: Surface dousp		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be cheeked		Remarks
1.	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e) <sub>+</sub>	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contruction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting-		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		140
~·)			

Overall Rating:

Satisfactory (S)	S	
Satisfactory but requires Inprovement (SRI)		
Unsatisfactory (U)		

(Signature) J. poro