


FIELD INSPECTION REPORT

Date of Inspection :- 10.12.20		District :- Khagoria
Division :- Khagoria		Length (Km) :- 1.0
Name of Road :- Alauli Hathwan R.E.O Road TO Chharafatti		
Scheme/Programme :- New M/R		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- Work Not started		Ongoing/Complete/Under Maintenance
Work is a case of :-		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contruccion Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 10/12/20
 J.E. Alauli