FIELD INSPECTION REPORT

Date of Inspection :- 08.12.2020		District:- Khagaeig	
Division: Hhapareh.		Length (Km):- (2.100 Km-	
Name of	Road: Gaura Shagts' REO,	Road Chananyam the To C	hatar Reference
	- Banch Kali Astho	n Characi Village.	
Scheme/Programme:- New JYP		Maintenance	
Package No.:-		Road ID No. :-	
Status of Project: - Trook not statted.		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up\radation/ Maintenance	
Sl. No.	Parameter	s to be cheeked	Remarks
1.	Pavement		the first way with
a)	Road Junction Condition		S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e) _	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contruction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		MA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		NA S/SRI/U
3.	Road Furniture		A Line
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone. Pavement road markings are provided and maintained		Yes/No
4.	Compliance History	and the second s	
a)	Status of ATR's & any others		
О́va	rall Rating : Satisfactory (S	(2)	NA

Satisfactory (S)	NA
Satisfactory but requires Inprovement (SRI)	
Unsatisfactory (U)	

(Signature) 08/12/2020 Khajarit.