


## FIELD INSPECTION REPORT

Date of Inspection :- 10.12.2020		District :- Khagaria.	
Division :- Khagaria		Length (Km) :- 0.570 Km.	
Name of Road :- NH-31 To Durgapur Paswan Talq.			
Scheme/Programme :- New RR		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- Work in progress.		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Upgradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	<b>Pavement</b>		
a)	Road Junction Condition		S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Construction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		NA S/SRI/U
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained		Yes/No
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)   
 10/12/2020  
 Khagaria.