FIELD INSPECTION REPORT

	FIELD INSPECTION REPORT		
Date of I	nspection: 4.12.20 District: Machebura		
Division	: Udakishan baros Length (km): 4.35KA.	0.000 0.200	A.
Name of	the Road: Const. of Rd. from P.W.D Rd to Thutha tola	parsidor	Ak:
Scheme/		592819	
Package		(20.)	
	the Project: Ongoing/Completed/Under Maintenance		
Work is	a case of: New Connectivity/Up gradation/ Maintenance	Remarks	
Sl. No.	Parameters to be cheeked		
1	Pavement	CAL	
a)	Road Junction condition	S/U	
<u> </u>	Condition of Surfacing	S/U	*
b)	700	s/U	
c)	Riding Quality	S/U	
d)	Road Camber	Y Olo	
e)	Whether free from defects such as visible cracks, exposed	Ýes/No	
<u> </u>	aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	In Progress.
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		N. Almot cow
and the prolinger of	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	1
a)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N·A
b)	Condition of Abuthlett & Willy Water, Bridges	S/SRI/U	N.A
c)	Condition of railings/slab/approach for Bridges Road Furniture	and the same of the	
3.	Road Furniture	A CONTRACTOR OF THE PARTY OF TH	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	1	772
4.	Compliance History	1/10	
a)	Status of ATR's & any others	1110	
Overall	Rating : Satisfactory (S)	S	

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	·

Work is trotal stage

(Signature)

Rason Jarosona sionad

NAME:

Biharoiganj

MIR OF PHID Laximiture to Parsiya Rd.





M/R OF PWD LAXMIPUR TO PARRIYA RD



