FIELD INSPECTION REPORT

DATE OF INSPECTION :- DIVISION :- TRIVENIGANI		DISTRICT	SUPAUL	UPAUL	
		CBaghell) W-B Road to Re			
NAMI	e of ROAD:- Rayhunathbur	r (Baghell) w	B Road to Raj	eswari	
SCHE	ME PROGRAMME	MAINTENANCE	MAINTENANCE		
PACKAGE NO. STATUS OF PROJECT:		Road Id No.: ONNGING/COMPLETED/UNDER MAINTENANCE			
					Work
Sl. No.	PARAM	MERERS TO BE CHECKED		REMARKS	
1	PAVEMENT MORE THE			CHAND	
a	Road junction condition			12 S/U	
b	Condition of Surface			MAS/U	
С	Riding Quality			MA S/U	
d	Road Camber			621AS/U	
е	Whether free fron defects such as visible cracks exposed aggregates in case of CC pavement			Yes/No	
f	Construction Joints provided or not (CC Pavement)			Yes/No	
g	Compaction of flank/ Slope & Rain cuts if any			Yes/No	
2	Cross Drainage				
a	Condition of head walls in Hume pipe culverts including its painting			MAS/SRI/U	
b	Condition of abutment & Wing walls, Slab in RCC culverts			AAS/SRI/U	
С	Condition of railings/slab/approach for Bridges			XAS/SRI/U	
3	Road Furniture				
a	Whether sign boards/informatory/cautionary Board/km & 200m stones/ Pavment road markings are provided and maintained			Yes/No	
3	Compliance History		work-on	Artesto	
a	status of ATR's & any Others			No Yes/No	
	Overall Rating :	Satisfactory (S)		M.D.	

Sweendog Rumar S. Do. R.W.D Chladelpin

Name

Signature

Satisfactory but requires Improvement

Unsatisfactory (U)

MA

NA