

FIELD INSPECTION REPORT

DATE OF INSPECTION :-		DISTRICT	SUPAUL
DIVISION :- TRIVENIGANJ		LENGTH (Km)	5.10km
NAME OF ROAD :- Rajeswari OP To Tamua			
SCHEME PROGRAMME		MAINTENANCE ✓	
PACKAGE NO.		Road Id No. :	
STATUS OF PROJECT :		ONNGING/COMPLETED/UNDER MAINTENANCE	
Work is a case of :		New Connectivity/ Up gradation/ Maintenance	
Sl. No.	PARAMERERS TO BE CHECKED		REMARKS
1	PAVEMENT		Work Not Started
a	Road junction condition		N.A S/U
b	Condition of Surface		N.A S/U
c	Riding Quality		N.A S/U
d	Road Camber		N.A S/U
e	Whether free from defectssuch as visible cracks exposed aggregates in case of CC pavement		N.A Yes/No
f	Construction Joints provided or not (CC Pavement)		N.A Yes/No
g	Compaction of flank/ Slope & Rain cuts if any		N.A Yes/No
2	Cross Drainage		Work Not Started
a	Condition of head walls in Hume pipe culverts including its painting		N.A S/SRI/U
b	Condition of abutment & Wing walls, Slab in RCC culverts		N.A S/SRI/U
c	Condition of railings/slab/approach for Bridges		N.A S/SRI/U
3	Road Furniture		
a	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained		N.A Yes/No
3	Compliance History		
a	Status of ATR's & any Others		Yes/No

Overall Rating :

Satisfactory (S)	N.A
Satisfactory but requires Improvement	N.A
Unsatisfactory (U)	N.A

Suresh Kumar
S. D-O RND
Chhatapur

Name

Suresh
10/12/20

Signature