FIELD INSPECTION REPORT

DATE OF INSPECTION :-		DISTRICT	SUPAUL	SUPAUL					
DIVISION :- TRIVENIGANJ		LENGTH (Km)							
NAME	Pakki Sarak to 8.5RD to 0 Ri	Road for The West	m Korizapetri, Rojes of Gangapur Minar Co	wari'					
SCHEME PROGRAMME PACKAGE NO. STATUS OF PROJECT:		MAINTENANCE Road Id No.: ONNGING/COMPLETED/UNDER MAINTENANCE							
					Work is a case of:		New Connectivity/ Up gradation/Maintenance		
					Sl.	PARAMERERS TO BE CHECKED		REM	IARKS
No.	PAVEMENT WORK not								
a	Road junction condition			TONA					
b	Condition of Surface			142					
С	Riding Quality			/U					
d	Road Camber			S/U					
е	Whether free fron defects such as visible cracks exposed aggregates in case of CC pavement			s/No					
f	Construction Joints provided or not (CC Pavement)			s/No					
ge	Compaction of flank/ Slope & Rain cuts if any			s/No					
2	Cross Drainage								
a	Condition of head walls in Hume pipe culverts including its painting			SRI/U					
b	Condition of abutment & Wing walls, Slab in RCC culverts			SRI/U					
С	Condition of railings/slab/approach for Bridges			SRI/U					
3	Road Furniture								
a	Whether sign boards/informatory/cautionary Board/km & 200m stones/ Pavment road markings are provided and maintained			A s/No					
3	Compliance History								
a	Status of ATR's & any Others		Hrke	s/No					

Overall Rating :

Satisfactory (S)	W-A
Satisfactory but requires Improvement	NA
Unsatisfactory (U)	IXA

Chatafax Name

Signature