

FIELD INSPECTION REPORT

Date of Inspection :	9.12.2020	District:	Punaha
Division :	Baisi	Length (km):	2.230 KM
Name of the Road:	Bhatbar to chikahi		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/ ☒ Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

work is in Progress

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

9/12/2020
A.B.
(Signature)
Baisa

NAME: