

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District: Purnia
Division :		Length (km):
Name of the Road: Khariga to Sahangan		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.: 21105408029
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

* Road is damaged in some ch. due to flood, except the part of damaged from flood rest Part of road is satisfactory. DPR of restoration Part is getting ready.

Pravraj Kumar
(Signature) 05/12/20

NAME: GAURAV KUMAR

DESIGNATION: ASSISTANT ENGINEER