## FIFLD INSPECTION REPORT

Date	of Inspection:	06-12,2030	District: Chapta	
Divis		Chopia-I	Length (km): 12.360 Km	
	e of the Road:	Monypur Months	in St Dopterpux	-
	me/rrogramme:	MAINTENANCE,		
ALL DE LABOR.	age No.:		Road Id No.:	
Status of the Project: Work is a case of:		New Connectivity/Up gradation/ Maintenance		sted
EXPRISE IN	THE PERSON NAMED IN STREET	THE PROPERTY OF THE PARTY OF TH	NITE THAT PROPERTY AND ADDRESS OF THE PARTY	
SI. N	The state of the s	Parametersto	by checked	Remark
1.	Pavement			Up of the
a)	Road Junction	condition		S/U
b)	Condition of St	urfacing		\$/U
c)	Riding Quality	The state of the s		S/U
d)	Road Camber			S/U
e)	Whether free aggregates in ca	from defects such se of CC Pavement.	as visible cracks, exposed	Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
测路	Cross Diagram			
a)	Condition of hea	d walls in Hume pip	e culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of rail	ings/slab/approach f	or Bridges	S/SRI/U
	Road Buringon			
1)			autionary Board/km & 200m rovided and maintained	Yes/No
	compliate (th			
)	Status of ATR's	any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	$\checkmark$
Unsatisfactory (U)	

8000 6-12.7020

(Signature)

NAME:

DESIGNATION: