FIELD INSPECTION REPORT

Date	f Inspection:	05-17,7070	District: Chara	
Divisio	And in case of the last of the	Chopsa-I	Length (km): 4. 166 Pm	
The second second second second	of the Road:	Loy5 Tenya S	ce Syan Chapma	
PER PROPERTY AND ADDRESS OF THE PARTY AND ADDR	e/Programme:	MAINTENANCE	,	
Packag	ge No.: BB	OPPROJE	Road Id No.:	
Status	of the Project:	Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Worki	s a case of:			
SI. No.		Parameters in	be checked	Remarks
1.5	Pavement			and history
a)	Road Junction	condition		SAU
b)	Condition of St	ırfacing		9/U
c)	Riding Quality	Control of the Contro	at part	S/U
d)	Road Camber			S/U
e)		from defects such use of CC Pavement.	as visible cracks, exposed	Yes/No
f)	Contraction Join	nts provided or not (C	CC Pavement)	Yes/No
g)	Compaction of	Tank/slope & raincuts	s if any	Yes/No
20.5	Oross Drainage			
a)	Condition of hea	d walls in Hume pipe	e culverts including its painting	S/SRI/U
b) ·	Condition of Ab	utment & Wing walls	s, Slab in RCC culverts	S/SRI/U
c)	Condition of rail	ings/slab/approach fo	or Brîdges	S/SRI/U
	Road Furniture			All part size
a) s	stones/Pavement	road markings are pr	utionary Board/km & 200m ovided and maintained	Yes/No
and the	diministrative constraints	one contract		No.
i) S	itatus of ATR's &	& any others		-

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

D-12-707,

(Signature)

NAME:

DESIGNATION: