FIELD INSPECTION REPORT

| Date | TI- | 一一一个生态。 | DEPARTS. |
|---------------------|--|---------|----------|
| Divisio | Inspection: 3 12 2000 District: Stwas | | |
| Name | of the Road: Toz Sarai Via Salitola in Approximate | 50 | |
| Scheme | אווע אווע אוויע | | 131 |
| Packag | - " Si diffine: MADVITENTANICIES | | |
| Status | of the Project: Orgoing/Completed/Under Maintenance | - | - |
| Work i | | | |
| Sl. No. | The second secon | | a = |
| A Survey of the San | Tarameters to be checked | Remarks | 4 |
| 1. | Pavement | | |
| a) | Road Junction condition | S/U | |
| b) | Condition of Surfacing | S/U | 1 |
| c) | Riding Quality | S/U | |
| d) | Road Camber | S/U | Dagor |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | 7 |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | NA |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3. | Road Furniture | | J |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | Yes |
| A | Compliance History | | |
| a) | Status of ATR's & any others | NO | |

Overall Rating

| | ` | |
|---|---------------|--|
| Satisfactory (S) | 3 | |
| Satisfactory but requires Improvement (SRI) | | |
| Unsatisfactory (U) | | |
| Salss | Salssfactory" | |

(Signature)

NAME:

DESIGNATION:

AND CAMPTER SE 2112/20 SE 2112/20 SE