

# FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020		District: Muzaffarpur	
Division : Muz - East - 2		Length (km): 3.242	
Name of the Road: Belson PWD Road to Turki Khararoo (13)			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	N.A
b)	Condition of Surfacing	S/U	N.A
c)	Riding Quality	S/U	N.A
d)	Road Camber	S/U	N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No =	N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N.A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Information Yes/No	Information seen Fixed
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating : Const. work not started

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N.A

05.12.2020  
(Signature)

NAME: Kamte Pal-Singh

DESIGNATION: JE Muzaffarpur