


FIELD INSPECTION REPORT

Date of Inspection : 5.12.2020		District: Muzaffarpur
Division: R.W.D. Muzaffarpur West		Length (km): 1.62 K-M
Name of the Road: Bishunpur Sarayu - Sarayu		
Scheme/Programme: MAINTENANCE		
Package No.: RM-MV-MV/19-0028		Road Id No.: 31507202056
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


(Signature)

NAME: K.K. Gupta

SIGNATURE: 