## FIELD INSPECTION REPORT

Date of Inspection: 05.12.2020 muza Harpin District: Division: Muz-East-2 Length (km): 4-107 Name of the Road: PlvD Sadan Primary thelth centre via Purcinia, Wheras to minapur pur sous. Scheme/Programme: MAINTENANCE Package No.: Road Id No.: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked Remarks 1. Pavement Road Junction condition S/U a) Condition of Surfacing b) S/U N.A c) Riding Quality S/U d) Road Camber S/U N.A Whether free from defects such as visible cracks, exposed c) Yes/No N.A aggregates in case of CC Pavement. n Contraction Joints provided or not (CC Pavement) Yes/No N.A Compaction of flank/slope & raincuts if any g) Yes/No N. A 2. **Cross Drainage** a) Condition of head walls in Hume pipe culverts including its painting S/SRI/U MA b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U N.A Condition of railings/slab/approach for Bridges c) S/SRI/U N.A" 3. Road Furniture Informatory sua Whether sign boards/informatory/cautionary Board/km & 200m Yes/No a) stones/Pavement road markings are provided and maintained 4. Compliance History a) Status of ATR's & any others Const Worn not started Overall Rating Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U) 05.12.2020

NAME: Kamte pel-Sings

DESIGNATION: JE minefur

(Signature)