

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Patna
Division :	Patna	Length (km):	1.750
Name of the Road:	NH-30 to Champapuri		
Scheme/Programme:	MAINTENANCE		
Package No.:	MRN/2019-20/Patna/02	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SC
b)	Condition of Surfacing	SC
c)	Riding Quality	SC
d)	Road Camber	SC
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SSR/SC
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSR/SC
c)	Condition of railings/slab/approach for Bridges	SSR/SC
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Agreement not done

Satisfactory (S)	NA
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

NAME: Hiranish Roy
DESIGNATION: Assistant Engineer

(Signature)