## FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020 District: Pruzaffarpun Division: Pruz - East - 2 Length (km): 3.58 Name of the Road: Minapur Prantend Antarget Rampur Hari to expapra ho here Grandhinager chown Janiwali sado MAINTENANCE Package No.: Road Id No .: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance SI. No. Parameters to be checked Remarks 1. Pavement a) Road Junction condition S/U N.A b)" Condition of Surfacing S/U N.A c) Riding Quality S/U M.A d) Road Camber S/U Whether free from defects such as visible cracks, exposed c) aggregates in case of CC Pavement. Yes/No N.A f) Contraction Joints provided or not (CC Pavement) Yes/No N.A Compaction of flank/slope & raincuts if any g) Yes/No N.A 2. Cross Drainage Condition of head walls in Hume pipe culverts including its painting a) S/SRI/U N.A b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U N.A . Condition of railings/slab/approach for Bridges c) S/SRI/U N.M 3. Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m Informet a) stones/Pavement road markings are provided and maintained Yes/No Dixed 4. Compliance History a) Status of ATR's & any others

Overall Rating

Const worn not started

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

05-/2-202 (Signature)

NAME: Kornta pel · Sigs

DESIGNATION: JE minapur