

FIELD INSPECTION REPORT

Date of Inspection : 09.12.2020		District: <i>Muzaffarpur</i>
Division : <i>Muzaffarpur West</i>		Length (km): <i>1.2</i>
Name of the Road: <i>Pravara Road</i>		
Scheme/Programme: MAINTENANCE		<i>Under the National Highway</i>
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S Yes/No
f)	Contraction Joints provided or not (CC Pavement)	<i>Not</i> Yes/No
g)	Compaction of flank/slope & raincuts if any	S Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<i>Not</i> S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<i>Not</i> S/SRI/U
c)	Condition of railings/slab/approach for Bridges	<i>Not</i> S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>Not</i> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<i>S</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

69.12.2020
(Signature)

NAME: *Jitendra Kumar*

DESIGNATION: *JE*