

FIELD INSPECTION REPORT

Date of Inspection :	10/12/20	District:	East Champaran
Division :	Mohi Kari	Length (km):	1.80
Name of the Road:	Kawalpur to Gubinapur Tikaita route		
Scheme/Programme:	MAINTENANCE	(OLD)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>out of maintenance</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE: - This road is completed on 25/3/14. At present this is out of maintenance

(Signature)

NAME: MAHESHWAR SHARMA

DESIGNATION: J.E.