

FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020		District: East Chhambharan
Division : Sikkharna (Dhaka)		Length (km): 2.250 km
Name of the Road: Baghi Bhelewa to dar		
Scheme/Programme: MAINTENANCE (New Maintenance Policy 2018)		
Package No.:		
Status of the Project:	Road Id No.: 31708602058	
Work is a case of:	Ongoing/Completed/Under Maintenance	
	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 10/12/2020

NAME: Mamd Gopal.
AE, RWD, Dhaka.