

FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020		District: East Champaran
Division : R.W.D (W) Dhaka		Length (km): 1.805
Name of the Road: Dhaka Belwaghat Road to Daudnager		
Scheme/Programme: MAINTENANCE New-3054		
Package No.: MR-N/19-20/Dhaka/22	Road Id No.: 31708602076	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NOTE:- Some Parts of Roads in 2nd KM are damaged due to flood during Heavy Rain/Flood damaged in year 2019-20 & 2020-21. But Road is Motorable & work is started.

(Signature)

NAME: Shesh Murul Hooda

DESIGNATION: A.E

10/12/2020
EE.