

FIELD INSPECTION REPORT

Inspection : 7/12/2020	District: East Champaran, Motihari
Works Division Pakhdayal	Length (km): 1.00 km
Road: Mathi Ya Chamba pur Road to Mohammadpur	
Programme: MAINTENANCE	New Maintenance Policy - 2018
o.:	Road Id No.:
Project: Ongoing/Completed/Under Maintenance	
Case of: New Connectivity/Up gradation/ Maintenance	

Parameters to be checked	Remarks
Pavement	
Road Junction condition	S/U NA
Condition of Surfacing	S/U NA
Riding Quality	S/U NA
Road Camber	S/U NA
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
Contraction Joints provided or not (CC Pavement)	Yes/No NA
Compaction of flank/slope & raincuts if any	✓ Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
Condition of railings/slab/approach for Bridges	S/SRI/U NA
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Sign Board Yes/No informatory B. fixed
Compliance History	
Status of ATR's & any others	NA

Rating :	'S'
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work in Progress
 S. E.
 7/12/2020
 J. E.

(Signature)
 7/12/2020