

FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	East Champaran
Division :	WORKS DIVN DHAKA	Length (km):	1.668 km
Name of the Road:	Motihari Dhaka PWD road to Misapur		
Scheme/Programme:	MAINTENANCE	(New Maintenance Policy)	
Package No.:		Road Id No.:	31708602115
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S/U
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

N.A

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

work not started by contractor

NAME:

Ramchandra Paswan

DESIGNATION:

Executive Engineer

09/12/2020

(Signature)

09/12/20

JE