

FIELD INSPECTION REPORT

Date of Inspection : 10.12.2020
 Division : R.W.D (W) Dhaka District: East Champaran
 Name of the Road: Pachpakri to Garabhiya Road Length (km): 4.929
 Scheme/Programme: MAINTENANCE New 2020
 Package No.: MR.N/19-20/Dhaka/22 Road Id No.: 31708602119
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRU/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU/U
c)	Condition of railings/slab/approach for Bridges	S/SRU/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NOTE: The work has been started. Some parts of roads in 2nd km, 3rd km, 4th km & 5th km are damaged due to flood during heavy rain/flood in year 2019-20 & 2020-21. But Road is maintainable.

NAME: Shesh Murali Hoda.

DESIGNATION: A-E

(Signature)

10/12/2020
 EF