

FIELD INSPECTION REPORT

Date of Inspection :	7/12/2020	District:	East Champaran, Motihari
Division :	WORKS Division Pakhichayal	Length (km):	1.350 km
Name of the Road:	Mathiya Champapur R.E.O Road To Mahanadpur Via Bara Sakhar		
Scheme/Programme:	MAINTENANCE	New Maintenance-2018	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Sign Board Yes/No Informatory Board
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	1 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work in Progress

Sakhar
7/12/2020
(Signature)

NAME: Sanwar Ali
DESIGNATION: S.E