

FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	District:	East Champaran, Motihari
Division :	WORKS DIV. Pakhridaya	Length (km):	6.200 Km
Name of the Road:	Grihuli To Gornahi		
Scheme/Programme:	MAINTENANCE	Road Id No.:	New Maintenance - 2018
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U NA
b)	Condition of Surfacing		S/U NA
c)	Riding Quality		S/U NA
d)	Road Camber		S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges		S/SRI/U NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Sign Board Yes/No Informatory Board
4.	Compliance History		
a)	Status of ATR's & any others		NA

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work in Progress

SAR
10/12/2020
(Signature)

NAME: Sarwar Ali

DESIGNATION: J.E