## FIELD INSPECTION REPORT

Date of Inspection : S	1/12/2020	District: East champaran	
Division: Works7	Division Parriday	Length (km): 1. 500K M	
	naghua To	San ya	
Scheme/Programme:	MAINTENANCE	New MainTenance - 2018	
Package No.:		Road Id No.:	
Status of the Project:	Queding/Completes	/Under Maintenance	
Work is a case of:	New Connectivity/I	p gradation/ Maintefiance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
n)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
n)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges S/SRI	
3.	Road Furniture	Sign Boo
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	res/Ng
4.	Compliance History	NA
п)	Status of ATR's & any others	

Overall Rating :

	NA
Satisfactory (S)	LYE
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

work not started

(Signature) 1/2/2020

NAME: Sarwar Alan

DESIGNATION: JE