

		FIELD INSPECTIO	N REPORT	
of Inspection: 7/12/2020 D			District:	
sion: Works Division Pakndayal Length (km): 2.00 K.m.				
ie of	the Road: Bo	Khri To Bhit gha	rwa	
eme/	Programme:	MAINTENANCE Ne	w maintenance -	2018
-	No.:	1.5.5.5	ad Id No.:	
10000	f the Project: a case of:	Ongoing/Completed/Und New Connectivity/Up gra		
No.	Parameters to be checked		Remarks	
	Pavement			
)	Road Junction condition			S/U N/A
)	Condition of Surfacing			S/U NA
)	Riding Quality			S/U N/A
)	Road Camber			STUNA
)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No MA
)	Contraction Joints provided or not (CC Pavement)			Yes/No AIA
)	Compaction of flank/slope & raincuts if any			Yes/No
) Jane	Gross Drainage			
Notice of	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U N
,	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U A
)	Condition of railings/slab/approach for Bridges			S/SRI/U N
(See)	Road Furnito	CONTRACTOR CONTRACTOR		Sign Board
)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained Supermatory of			
,		CONTRACTOR OF THE PARTY OF THE		4
1	Status of ATR's & any others			NA
)	Status of ATR	's & any others		
erall Rating : Satisfactory (S)			151	
CIMII	Ramb	Satisfactory (S)	res Improvement (SRI)	
		Unsatisfactory (U)		
. 1	vone in pro	Unsatisfactory (U) gress State 200	(Sig	nature)