

FIELD INSPECTION REPORT

New Mandla (2024)

Date of Inspection:	07/12/24	District:	Motihari
Division:	Pakari Jagad	Length (Km):	2.0
Name of Road:	Dharmaji Baraot Das math to Sihahi		
Scheme/Programme:	Maintenance ✓		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓	S/U
b)	Condition of Surfacing	✓	S/U
c)	Riding Quality	✓	S/U
d)	Road Camber	✓	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓	Yes/No
g)	Compaction of flank /slope & raincuts if any	✓	Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts		S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/ informative/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓	Yes/No
3	Compliance History		
a)	Status of ATR's & any others		
Overall Rating:			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

Name:
Designation:

[Signature]
09/12/24
(Signature)