## FIELD INSPECTION REPORT e of Inspection: 8/12/2020 District: East champ aran Moti hari sion: Works Division Pakndayal Length (km): 1.400 K.m ne of the Road: KhaTauna Avdhesh Singh House To Bhaxamsth eme/Programme: MAINTENANCE New main Tenance - 2018 Road Id No .: kage No.: tus of the Project: Qugoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance rk is a case of: No. Parameters to be checked Remarks Pavement S/U MA Road Junction condition S/U MA Condition of Surfacing S/U NA Riding Quality S/U NA Road Camber Whether free from defects such as visible cracks, exposed Yes/No NI aggregates in case of CC Pavement. Yes/No NA Contraction Joints provided or not (CC Pavement) Yes/No NA Compaction of flank/slope & raincuts if any Gross Drainage Condition of head walls in Hume pipe culverts including its painting S/SRI/U MA S/SRI/U N/A Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U NA Condition of railings/slab/approach for Bridges Road Furniture Sign Board Yes/No Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History MA Status of ATR's & any others MA verall Rating Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U) WORK NOT STATEd