

FIELD INSPECTION REPORT

Date of Inspection:	09/12/XX	District:	Motihari
Division:	Patna Division	Length(Km):	
Name of Road:	Bihar in Muzilal Rai Kowda Haranpur River		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/ Informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No	
3	Compliance History		
a)	Status of ATR's & any others		
Overall Rating:			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory (U)			

Name:
Designation:

[Signature]
(Signature)

Not Stated