FIELD INSPECTION REPORT

Date of Inspection: 10.12.2020			District: East champaran		
Division: paknidyaj			Length (km): 1.10		
Name o	of the Road: ph	enhara gjorbar	a to biobindbara		
	e/Programme:	MAINTENANCE	MR 3054 (New maintenance	policy 2018	
Packag		11	Road Id No.:		
	of the Project:		/Under Maintenance		
	s a case of:		Jp gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement				
(a)	Road Junction condition			S/U NA	
b)	Condition of Surfacing			S/U NA	
c) -	Riding Quality	S/U NA			
d)	Road Camber	S/U NA			
e)	Whether free aggregates in ca	Yes/No NA			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No M	
g)	Compaction of flank/slope & raincuts if any			Yes/No NA	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U N	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U ^	
c)	Condition of railings/slab/approach for Bridges			S/SRVU r	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4,11	Compliance History				
a)	Status of ATR's & any others			MA	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	All from
Unsatisfactory (U)	

work not start yet

10.12.2020

(Signature)

NAME: Dharmentra Kumar

DESIGNATION: JE