FIELD INSPECTION REPORT

ate of Inspection: 08/12/020 Wision: Thankarpur			District: Machubanz Length (km): 2.510 km	
ime of th	e Road: g		ram to Janking ou.	
heme/Pr	ogramme:	MAINTENANCE		
ickage N			Read Id No.:	
atus of the Project: Ongoing/Comple		Ongoing/Complet	ed/Under Maintenance In Henole	in proc
Vork is a	case of:	New Connectivity	/Up gradation/ Maintenance focet	
SL No.	L No. Parameters to I		to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
0)	Riding Quality			S/U
(b)	Road Camber			S/U
(e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
0	Contraction Joints provided or not (CC Pavement)			Yes/No
1 82	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
(a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
(b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRL/U
()	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			1
13)	Status of ATR's & any others			
Over	Il Rating	1		
Orda		Satisfactory	but requires Improvement (SRI)	
		Unsatisfact	The state of the s	The state of

(Signature)

NAME: ASLOK L'M. Gaylory DESIGNATION: Jr. eyener