FIELD INSPECTION REPORT

-			The state of the s	
	Inspection:	10/12/20	District: Samuel	1.4
Division: Somastifur			Length (km): 6.50	WY
Name o	of the Road: A	DRd Burkets	to Anayyada melasi Ro	
Scheme	:/Programme:	MAINTENANCE	Type The Man Pe	
Packag		T	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
i.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			TO THE TE
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a) S	Status of ATR's	& any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

274

Courtain Den

(Signature)

NAME:

Market Service

Jo