

# FIELD INSPECTION REPORT

|                        |                                            |              |            |
|------------------------|--------------------------------------------|--------------|------------|
| Date of Inspection :   | 10/12/20                                   | District:    | Semantipur |
| Division :             | Semantipur                                 | Length (km): | 6.15       |
| Name of the Road:      | Thare Adichugat Bhowan to Gopalpur         |              |            |
| Scheme/Programme:      | MAINTENANCE                                |              |            |
| Package No.:           | -                                          | Road Id No.: | 320/010289 |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |            |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |            |

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | Pavement                                                                                                             |         |
| a)      | Road Junction condition                                                                                              |         |
| b)      | Condition of Surfacing                                                                                               | S/U     |
| c)      | Riding Quality                                                                                                       | S/U     |
| d)      | Road Camber                                                                                                          | S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | S/U     |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No  |
| 2.      | Cross Drainage                                                                                                       | Yes/No  |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U |
| 3.      | Road Furniture                                                                                                       |         |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No  |
| 4.      | Compliance History                                                                                                   |         |
| a)      | Status of ATR's & any others                                                                                         |         |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

NAME:

Gautam Das  
J.E

  
10/12/20  
(Signature)