FIELD INSPECTION REPORT

ſ	Da	te of Inspection: /	11101-	District: SAMALTE	
_	Division: SAMI		ASTIPUR 1		PUP
	Name of the Road:				
1	Scheme/Programme: MAINTENANCE			rokhara lima	
	Lond L. At			C.D	
S	Ongoing/Completed/Under Maint		nder Maintenance		
V	violatia case of: Ne		ew Connectivity/Up gradation/ Maintenance		
S	SILNO.		Parameters is best and the second of the seco		
	1.	Pavement		YILEKEU	Remarks
	a) Road Junction condition				
	b)			S/U	
			racing		S/U
-	<i>)</i>	Riding Quality			S/Ü
d)	Road Camber			S/Ü
e)		Whether free	3/0		
7		aggregates in cas	of CC Pavement.	natione cracks, expose	Yes/No
(t	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any		iy	Yes/No g	
2		Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/II		
b)		Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)		Condition of railings/slab/approach for Bridges			S/SRI/U
3,	R	load Furniture			
a)	X sta	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	C	mpliance Histor			
a)	Sta	tus of ATR's & a	A. A. C.		
				,	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 12/2020